

Water Main Plan



LEGEND

Clean network:	Sluice valve	Stop tap
Pressure reducing valve		Water Treatment Works
Meter		Water Pumping Station
Bulk meter		Existing main
Hydrant		Non-operational main
Cap end		Raw Water
Air valve		

NB: Water main symbol colour indicates the type.
 LIGHT BLUE - Trunk
 DARK BLUE - Distribution
 YELLOW - Raw Water

Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Dŵr Cymru Cylfyngedig (the Company) gives this information as to the position of its underground apparatus by way of general guidance only and on the understanding that it is based on the best information available and is not warranted as to its correctness in the event of excavations or other works made in the vicinity of the Company's apparatus. The error of location of apparatus is liable to vary and any excavations made entirely on your own. The information which is supplied by the Company is done so in accordance with statutory requirements of sections 103 and 109 of the Water Industry Act 1991 which is based upon the best information available and, in particular, but without prejudice to the generality of the foregoing, it should be noted that the records that are available to the Company may not indicate the existence of water mains, service pipes, drains, sewerage pipes or other apparatus and any excavations made in the vicinity of the Company's apparatus should be made with caution and the position of any apparatus should be ascertained by other means. It must be understood that the furnishing of this information is entirely without prejudice to the provisions of the New Roads and Street Works Act 1991 and the Company's rights to be compensated for any damage to its apparatus.

Service pipes are not generally shown but their presence should be anticipated.

**EXACT LOCATIONS OF ALL APPARATUS
TO BE DETERMINED ON SITE.**

Reproduced by permission of the Ordnance Survey on behalf of
 HMSO. © Crown copyright and database right 2017.
 All rights reserved.
 Ordnance Survey Licence number 100019534

Map Ref: 305033,207648
 Map scale: 1:1500
 Printed by: Natalie Walmsley
 Printed on: 11 Jan 2022

