

Appendix 9.5 Part 2 of 2 - Site visit photographs



P044 – possible karstic feature



P045 – vegetation associated with ponding water



P046



P047 – seepages in western face



P048 – shale bed interbedded with limestone



P049



P050 – shale bed in limestone



P051 – waterfall – continuation of water from northern part of eastern arm



P052



P053 – main flow of water in eastern arm



P054



P055 – moss and vegetation on face suggest water flows during wet period



P056



P057 – quarry floor looking south



P058 – water fall and main flow of water looking south



P059 – karstic feature in eastern wall





P060 – main flow of water running south



P061 – waterfall in lower bench




P062 – main water flowing south



P063 – seepages along bedding planes



P064 – bedding plane seepage



P065 – seepages and fractures





P066



P067 – ponding of water sourced from main flow of water from north



P068 – view of eastern arm from south looking north



P069 – pond in SE of eastern arm



P070 – gauge board in SE pond



P071 – track adjacent to pond



P072



P073



P074 – pond in SE of eastern arm



P075 – gauge board in SE pond





P076



P077 – southern end of SE pond



P078



P079 – looking south from southern end of pond



P080



P081 – view looking north from southern end of pond



P082 – looking north across pond



P083 – flow of water to pond

Vaynor Quarry Site Visit: Processing Area

21 NOVEMBER 2019



P084 – culvert in south



P085 – flow of water towards culvert



P086 – flow of water towards culvert



P087 – flow of water towards culvert, water mostly flowing around and not through the pipes



P088 – source of water flowing southwards



P089 – view looking north



P090



P091