

Former St. Tydfil's
Hospital

Listed Building Room Data &
Photographic Record

Project Ref: 2447

21 September 2020

MERTHYR TYDFIL
COUNTY BOROUGH
COUNCIL
**OFFICE COPY
PLEASE DO NOT
REMOVE**

200234


MTCBC
PLANNING DEPARTMENT
- 7 OCT 2020
RECEIVED

Architecture
Civil Engineering
Structural Engineering
Urban Design
Transport

Ground Floor

Room Number: GF1

Room Description: Entrance Lobby



Room Data

Element	Condition (G/F/P)	Comments
Walls	F	Stone
Floor	P	Stone/concrete - access not possible
Ceiling/Roof	G	Painted timber boarding
Doors	F/P	External door missing
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other		Access not possible for photograph of east wall



West Wall



South Wall



North Wall



Ceiling




Floor


Ground Floor

Room Number: GF2

Room Description: Entrance Hall



Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick.
Floor	F	Polished patterned concrete/terrazzo
Ceiling/Roof	P	Lath and plaster remnants above remnants of modern suspended ceiling
Doors	F/P	Internal doors & architraves missing. Arched timber double door to GF1 within simple rebated surround. Modern fire escape door in east wall.
Windows		See Separate Window Survey
Fixtures & Fittings	F	Cast iron radiator & pipework. Cast concrete staircase with cast iron balusters & polished steps - see next page for staircase details
Other	F	Moulded skirting board in places - see next page



East Wall



West Wall & Ceiling



North Wall



South Wall






Floor Detail

Ground Floor

Room Number: GF2


Room Description: Entrance Hall



Ground Floor

Room Number: GF3

Room Description: Internal Corridor



Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick.
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/Roof	P	Lath and plaster remnants above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Modern bullnose skirting - not original



Ceiling




View north along corridor

Ground Floor

Room Number: GF4

Room Description: General Office?



Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick.
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/Roof	P	Damaged lath and plaster above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Moulded skirting partly missing - appears not original



Ceiling



Ceiling




North Wall



East Wall



South Wall




West Wall

Ground Floor

Room Number: GF5

Room Description: Internal Corridor



Room Data		
Element	Condition (G/F/P)	Comments

Walls	P	Peeling paint on plastered brick.
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/Roof	P	Damaged lath and plaster above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other		Modern bullnose skirting - not original



Ceiling



East Wall



West Wall




North Wall



South Wall



Looking south into WC




Ceiling



Looking west into WC

Ground Floor
Room Number: GF6
Room Description: WC




Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick.
Floor	P	Not visible due to collapsed ceiling
Ceiling/ Roof	P	Remnants of lath and plaster above remnants of modern suspended ceiling
Doors	F	Modern flush door & bullnose architrave to inner WC
Windows		See Separate Window Survey
Fixtures & Fittings	P	Porcelain sink & WC
Other	P	Modern bullnose skirting - not original

Ground Floor


Room Number: GF7

Room Description: General Office?



Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone
Floor	P	Linoleum floor tiles - all peeling
Ceiling/ Roof	P	Unfinished plasterboard between fire protected downstand beams above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing. Modern flush external door within simple rebated frame.
Windows		See Separate Window Survey
Fixtures & Fittings	F	Cast iron radiator
Other	P	Modern bullnose skirting - not original



Ceiling




Ceiling



North Wall



East Wall



South Wall




West Wall

Ground Floor

Room Number: GF8

Room Description: General Office?



Ceiling



Ceiling



North wall



East Wall



South Wall




West Wall

Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/ Roof	P	Remnants of unfinished plasterboard between timber-clad downstand beams above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing. Modern flush external door within simple rebated frame.
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Modern bullnose skirting - not original

Ground Floor

Room Number: GF9

Room Description: Connecting Lobby




Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick.
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/Roof	P	Damaged lath and plaster above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Modern bullnose skirting - not original



Ground Floor

Room Number: GF10

Room Description: General Office?



Room Data


Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/ Roof	P	Damaged lath and plaster above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows		See Separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Modern bullnose skirting - not original



Ground Floor

Room Number: GF11

Room Description: General Office?



Room Data


Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone
Floor	P	Scant remnants of linoleum floor tiles on apparently solid floor
Ceiling/ Roof	P	Remnants of plasterboard ceiling above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows		See Separate Window Survey
Fixtures & Fittings	F/P	Cast iron radiators & pipework
Other	P	Modern bullnose skirting - not original




Ground Floor

Room Number: GF12

Room Description: Internal Lobby



Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone. Partly tiled with most tiles having fallen
Floor	P	Not visible due to rubble but a collapsed drainage inspection chamber is visible
Ceiling/ Roof	P	Remnants of lath and plaster ceiling above remnants of modern suspended ceiling
Doors	P	Internal doors & architraves missing.
Windows	F	Access not possible but part of non-listed element to be demolished
Fixtures & Fittings	P	Worktop & cupboards are visible but not accessible
Other	P	Modern bullnose skirting - not original



Looking south into GF12

Collapsed drainage inspection chamber in floor




Looking east into GF13

Ground Floor

Room Number: GF13

Room Description: Office/Store?



Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone.
Floor	P	Not visible due to rubble
Ceiling/ Roof	P	Not visible but seemingly mostly collapsed
Doors	P	Internal doors missing. Modern architraves & frames
Windows		Access not possible due to dangerous ceiling but part of non-listed element to be demolished
Fixtures & Fittings	P	Access not possible—none visible
Other	P	Access not possible—not visible



Looking west into GF14



Collapsed ceiling & floor above




Floor

Ground Floor

Room Number: GF14

Room Description: General Office?




Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone.
Floor	P	Not visible due to rubble
Ceiling/ Roof	P	Scant remnants of lath & plaster. Floor above col-lapsed
Doors	P	Internal & external doors missing. Modern archi-traves & frames
Windows		Access not possible due to dangerous ceiling but part of non-listed element to be demolished
Fixtures & Fittings	P	Access not possible—none visible
Other	P	Access not possible—not clearly visible



Ground Floor

Room Number: GF15

Room Description: Reception Office




Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick, stone & timber panelling
Floor	P	Suspended timber floor covered with modern ply boards & clear evidence of dry rot
Ceiling/ Roof	P	Papered lath & plaster ceiling. Badly damaged with holes revealing mixture of timber and concrete floor structure above.
Doors	P	Internal doors & architraves missing.
Windows		Stone Tracery. See Separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Modern moulded skirting - not original



First Floor

Room Number: FF1

Room Description: Landing & Staircase



Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone. Evidence of demolished partitions.
Floor	P	Timber floor covered with ply boards. Unfinished.
Ceiling/ Roof	P	Lath & plaster ceiling entirely missing. Small areas of badly damaged painted plasterboard remain.
Doors	P	Internal doors & architraves missing.
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Timber staircase to second floor - clearly not original. Various skirting mouldings.



East Wall



West Wall



North Wall



South Wall




North Wall




South Wall

First Floor
Room Number: FF2
Room Description: Internal Corridor




Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick. Evidence of demolished partitions.
Floor	P	Timber floor covered with ply boards. Unfinished.
Ceiling/ Roof	P	Remnants of lath and plaster ceiling above remnants of modern suspended ceiling
Doors	P	Internal doors missing.
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting boards & architraves to archway and doorways - see detail photo



First Floor

Room Number: FF3

Room Description: General Office?



Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone.
Floor	P	Carpeted timber floor.
Ceiling/ Roof	P	No ceiling - only ceiling chords remain
Doors	P	Internal doors missing.
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting boards & architraves to doorway



Ceiling & open roof above



View to north-east showing floor & ceiling



North Wall



East Wall



South Wall




West Wall

First Floor

Room Number: FF4

Room Description: Fire Exit Lobby



Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone.
Floor	P	Timber floor covered with ply boards. Unfinished.
Ceiling/ Roof	P	Remnants of lath and plaster ceiling
Doors	P	Internal doors & architraves missing. Simple modern rebated frame to external door.
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting boards remain in places - See Detail



Ceiling



Floor & Skirting Detail



View East



View West



North Wall




South Wall

First Floor

Room Number: FF5

Room Description: Store Room?



Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone.
Floor	P	Timber floor. Covering not visible due to collapsed ceiling debris. Room not accessible due to unsafe floor.
Ceiling/ Roof	P	No ceiling—remnants of roof insulation from open roof above
Doors	P	Door & architrave missing.
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting boards remain



West & South Walls




West & North Walls


First Floor

Room Number: FF6

Room Description: General Office?




Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone.
Floor	P	Timber floor covered with ply boards. Unfinished.
Ceiling/ Roof	P	Sloping lath & plaster ceiling to lowered eaves. No flat ceiling remains, with open roof above. A timber domed structure, presumably a lighting reflector, is present in the centre of the ceiling.
Doors	P	Door missing into room but moulded architrave remains on internal side of door lining. Modern flush door and architrave to FF7
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting boards remain in part



First Floor


Room Number: FF7

Room Description: General Office?



Room Data


Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone. Evidence of partitions now demolished.
Floor	P	Timber floor covered with ply boards. Unfinished with significant damage
Ceiling/ Roof	P	Remnants of lath & plaster ceiling with open roof above. A timber domed structure, presumably a lighting reflector is present in centre of ceiling.
Doors	P	Door missing into room but moulded architrave remains on internal side of door lining. Modern flush door and architrave to FF6
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting boards remain in part



First Floor

Room Number: FF8

Room Description: Toilets/Sluice?



Room Data


Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone. Partly tiled. Evidence of partitions now demolished.
Floor	P	Timber floor covered with ply boards. Partly surfaced in linoleum & remainder unfinished
Ceiling/ Roof	P	Scant remnants of lath & plaster ceiling with open roof above.
Doors	P	Door missing into room but modern architrave remains on internal side of northern most door lining.
Windows		See separate Window Survey
Fixtures & Fittings	P	Remains of porcelain sanitary ware
Other	P	Modern skirting boards remain in part



First Floor



Room Number: FF9

Room Description: General Offices?




Room Data

Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone. Timber panelling on all 4 walls in poor condition. Evidence of partitions now demolished.
Floor	P	Timber floor with ply boards & evidence of carpet but largely covered in collapsed ceiling debris
Ceiling/ Roof	P	Scant remnants of plasterboard ceiling between steel down-stand beams.
Doors	P	Internal doors & architraves missing. Door & access to rooms to south blocked.
Windows		See separate Window Survey
Fixtures & Fittings	F/P	Original ventilators in eastern wall - damaged
Other	P	Moulded skirting & window plinth in west wall



First Floor
Room Number: FF9
Room Description: General Offices?




Location of extant timber panelling

Location of original vents



Vents in East Wall



North-West Wall Corner



South Wall Panelling Detail



Panel Detail



Panel Detail




North Wall Panelling



South Wall Panelling



West Wall Window Plinth




South-West Wall Corner


Second Floor

Room Number: SF1

Room Description: Landing & Staircase




Room Data		
Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone and to damaged timber frame flat-roof dormer addition. West wall partition heavily damaged.
Floor	P	Timber floor with ply boards & evidence of fire damage on stairs.
Ceiling/ Roof	P	Skimmed & painted plasterboard to flat-roof dormer with rooflight
Doors	P	Internal door to SF2 missing. Modern bullnose architrave
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	F/P	Moulded skirting



Second Floor


Room Number: SF2

Room Description: General Offices?



Room Data


Element	Condition (G/F/P)	Comments
Walls	P	Peeling paint on plastered brick & stone. Carved timber tracery remaining in end bays of north and south walls
Floor	P	Timber floor with mixture of floorboards & replacement ply boards
Ceiling/ Roof	F/G	Timber panelling with exposed rafters and purlins
Doors	P	Internal door & architrave missing. Door opening damaged.
Windows		See separate Window Survey
Fixtures & Fittings	N/A	
Other	P	Moulded skirting & low window plinth in west wall



Second Floor

Room Number: SF2

Room Description: General Offices?



North

— Location of carved timber tracery

○ Location of kneelers



North Wall (Western-most bay)



North Wall (Eastern-most bay)



South Wall (Eastern-most bay)



South Wall (Western-most bay)



Typical Roof Bay



Kneeler



Door Opening



Window Plinth



Unit 2
Chapel Barns
Merthyr Mawr
Bridgend
CF32 0LS

T: 01656 656267
W: www.spring-consultancy.co.uk

Architecture
Civil Engineering
Structural Engineering
Urban Design
Transport

