



Area where
SO05045027 and all
the others are meant
to be located. Unable
to find any.

07/11/2019



SO05044004 is in the
verge

07/11/2019

Cover has been
stolen

07/11/2019

07/11/2019

Inside SO05044004,
825mm trunk main



Again, area where
SO05045027SO0504
4004 and all the
300mm sewers are
meant to be, unable
to locate any.

07/11/2019

SO05044023 is the
only chamber we
could find on the
300mm sections.

07/11/2019



SO05044023 is full of
rubble, but confirmed
this drops into
825mm main in
SO05044004

07/11/2019

SO05044004 over
825mm trunk is 3.5m
deep.



07/11/2019



07/11/2019

Entire area is full of rubble

07/11/2019



07/11/2019



Most chambers have
been filled in.

07/11/2019



07/11/2019



07/11/2019



07/11/2019



07/11/2019



07/11/2019



07/11/2019



SO05044121, cover
has been stolen so
concrete over it, can
hear the flow in the
trunk sewer, as per
plan

07/11/2019



07/11/2019



SO05043301

SO05043201

07/11/2019



SO05043201 over
trunk sewer.

07/11/2019



Flow inside
SO05043201

07/11/2019



SO05043201

07/11/2019



SO05043301

07/11/2019

Inside SO05043301

07/11/2019



SO05043411 over
the storm

SO05043499 over
trunk sewer.

07/11/2019



An underwater photograph showing a dark, rocky chamber. A red arrow points from a text box to a horizontal platform in the center of the frame. The chamber is surrounded by water and some hanging roots or cables. The lighting is dim, and the water appears slightly murky.

Inside SO05043499,
unable to see flow as
there is a platform in
this chamber and it is
offset.

07/11/2019



SO05043411
over the storm

07/11/2019



Inside SO05043411

07/11/2019

07/11/2019

Dye tested
SO05043004 beside
houses and
confirmed 150mm VC
sewer connected to
SO05044004



Locate an uncharted chamber next to entrance whilst looking for SO05045001

SO05045001 is just off the path in this overgrown area.



07/11/2019

07/11/2019

Pushed D/S approx
2m onto the 825mm
Trunk sewer

