

# APPENDIX I

COPY OF THE COAL  
AUTHORITY'S REPORT  
51001019337002



*The Enterprise Centre,  
Merthyr Industrial Park,  
Pentrebach,  
Merthyr Tydfil,  
South Wales,  
CF48 4DR.*

**BLANDFORD CONSULTING**

*Geologists Working With The Environment...*

Issued by:

The Coal Authority, Property Search Services, 200 Lichfield Lane, Berry Hill, Mansfield, Nottinghamshire, NG18 4RG  
Website: www.groundstability.com Phone: 0345 762 6848 DX 716176 MANSFIELD 5

**LANDMARK INFORMATION GROUP  
LIMITED  
SOWTON INDUSTRIAL ESTATE  
ABBEY COURT  
UNIT 5/7 EAGLE WAY  
EXETER  
DEVON  
EX2 7HY**

Our reference: **51001019337002**  
Your reference: **74218585\_2**  
Date of your enquiry: **27 October 2015**  
Date we received your enquiry: **27 October 2015**  
Date of issue: **27 October 2015**

This report is for the property described in the address below and the attached plan.

### Non-Residential Coal Authority Mining Report

#### SITE AT TYNEWYDD, BRONDEG, HEOLGERRIG, MERTHYR TYDFIL,

This report is based on and limited to the records held by, the Coal Authority, and the Cheshire Brine Subsidence Compensation Board's records, at the time we answer the search.

|                             |                    |
|-----------------------------|--------------------|
| Coal mining                 | See comments below |
| Brine Compensation District | No                 |

#### Information from the Coal Authority

##### Underground coal mining

###### Past

According to the records in our possession, the property is not within the zone of likely physical influence on the surface from past underground workings.

However the property is in an area where the Coal Authority believe there is coal at or close to the surface. This coal may have been worked at some time in the past. The potential presence of coal workings at or close to the surface should be considered prior to any site works or future development activity. Your attention is drawn to the Comments on Coal Authority Information section of the report.

###### Present

The property is not in the likely zone of influence of any present underground coal workings.

###### Future

The property is not in an area for which the Coal Authority is determining whether to grant a licence to remove coal using underground methods.

The property is not in an area for which a licence has been granted to remove or otherwise work coal using underground methods.

The property is not in an area that is likely to be affected at the surface from any planned future workings.

However, reserves of coal exist in the local area which could be worked at some time in the future.

No notice of the risk of the land being affected by subsidence has been given under section 46 of the Coal Mining Subsidence Act 1991.

#### **Mine entries**

There are no known coal mine entries within, or within 20 metres of, the boundary of the property.

#### **Coal mining geology**

The Authority is not aware of any evidence of damage arising due to geological faults or other lines of weakness that have been affected by coal mining.

#### **Opencast coal mining**

##### **Past**

The property is not within the boundary of an opencast site from which coal has been removed by opencast methods.

##### **Present**

The property does not lie within 200 metres of the boundary of an opencast site from which coal is being removed by opencast methods.

##### **Future**

The property is not within 800 metres of the boundary of an opencast site for which the Coal Authority is determining whether to grant a licence to remove coal by opencast methods.

The property is not within 800 metres of the boundary of an opencast site for which a licence to remove coal by opencast methods has been granted.

#### **Coal mining subsidence**

The Coal Authority has not received a damage notice or claim for the subject property, or any property within 50 metres, since 31st October 1994.

There is no current Stop Notice delaying the start of remedial works or repairs to the property.

The Authority is not aware of any request having been made to carry out preventive works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991.

#### **Mine gas**

There is no record of a mine gas emission requiring action by the Coal Authority within the boundary of the property.

#### **Hazards related to coal mining**

The property has not been subject to remedial works, by or on behalf of the Authority, under its Emergency Surface Hazard Call Out procedures.

#### **Withdrawal of support**

The property is not in an area for which a notice of entitlement to withdraw support has been published.

The property is not in an area for which a notice has been given under section 41 of the Coal Industry Act 1994, revoking the entitlement to withdraw support.

#### **Working facilities orders**

The property is not in an area for which an Order has been made under the provisions of the Mines (Working Facilities and Support) Acts 1923 and 1966 or any statutory modification or amendment thereof.

#### **Payments to owners of former copyhold land**

The property is not in an area for which a relevant notice has been published under the Coal Industry Act 1975/Coal Industry Act 1994.

### **Comments on Coal Authority information**

In view of the mining circumstances a prudent developer would seek appropriate technical advice before any works are undertaken.

Therefore if development proposals are being considered, technical advice relating to both the investigation of coal and former coal mines and their treatment should be obtained before beginning work on site. All proposals should apply good engineering practice developed for mining areas. No development should be undertaken that intersects, disturbs or interferes with any coal or mines of coal without the permission of the Coal Authority. Developers should be aware that the investigation of coal seams/former mines of coal may have the potential to generate and/or displace underground gases and these risks both under and adjacent to the development should be fully considered in developing any proposals. The need for effective measures to prevent gases entering into public properties either during investigation or after development also needs to be assessed and properly addressed. This is necessary due to the public safety implications of any development in these circumstances.

### ***Information from the Cheshire Brine Subsidence Compensation Board***

The property lies outside the Cheshire Brine Compensation District.

### ***Additional Remarks***

Information provided by the Coal Authority in this report is compiled in response to the Law Society's Con29M Coal Mining and Brine Subsidence Claim enquiries. The said enquiries are protected by copyright owned by the Law Society of 113 Chancery Lane, London WC2A 1PL. Please note that Brine Subsidence Claim enquiries are only relevant for England and Wales. This report is prepared in accordance with the Law Society's Guidance Notes 2006, the User Guide 2006 and the Coal Authority and Cheshire Brine Board's Terms and Conditions applicable at the time the report was produced.

The Coal Authority owns the copyright in this report. The information we have used to write this report is protected by our database right. All rights are reserved and unauthorised use is prohibited. If we provide a report for you, this does not mean that copyright and any other rights will pass to you. However, you can use the report for your own purposes.

## Location map



Approximate position  
of property



## Enquiry boundary

Reproduced by permission of Ordnance Survey  
on behalf of HMSO. © Crown copyright and  
database right 2015. All rights reserved.  
Ordnance Survey Licence number: 100020315

## Key

Approximate position of enquiry  
boundary shown

