

## Section 2 – Investigative or remedial activity

Please refer to the 'Summary of findings' map (on separate sheet) for details of any activity within the area of the site boundary.

### Site investigations

| Distance to site investigation (m) | Direction |
|------------------------------------|-----------|
| Within                             | N/A       |

See Section 4 for further information.

### Remediated sites

None recorded within 50 metres of the enquiry boundary.

### Coal mining subsidence

The Coal Authority has not received a damage notice or claim for the subject property, or any property within 50 metres of the enquiry boundary, since 31 October 1994.

There is no current Stop Notice delaying the start of remedial works or repairs to the property.

The Coal Authority is not aware of any request having been made to carry out preventive works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991.

### Mine gas

None recorded within 500 metres of the enquiry boundary.

### Mine water treatment schemes

None recorded within 500 metres of the enquiry boundary.

## Section 3 – Licensing and future mining activity

### Future underground mining

None recorded.

### Coal mining licensing

None recorded within 200 metres of the enquiry boundary.

### Court orders

None recorded.

### Section 46 notices

No notices have been given, under section 46 of the Coal Mining Subsidence Act 1991, stating that the land is at risk of subsidence.

### Withdrawal of support notices

The property is not in an area where a notice to withdraw support has been given.

The property is not in an area where a notice has been given under section 41 of the Coal Industry Act 1994, cancelling the entitlement to withdraw support.

### Payments to owners of former copyhold land

The property is not in an area where a relevant notice has been published under the Coal Industry Act 1975/Coal Industry Act 1994.

## Section 4 – Further information

The following potential risks have been identified and as part of your risk assessment should be investigated further.

### Development advice

The site is within an area of historical coal mining activity. Should you require advice and/or support on understanding the mining legacy, its risks to your development or what next steps you need to take, please contact us.

### Site investigations

The site is within an area of previous interest. It is close to where the Coal Authority has received information relating to past site investigations.

The site requires further investigation and may influence how you approach your risk assessment.

**For further information on specific site or ground investigations in relation to any issues raised in Section 4, please call us on 0345 762 6848 or email us at [groundstability@coal.gov.uk](mailto:groundstability@coal.gov.uk).**

## Section 5 – Data definitions

The datasets used in this report have limitations and assumptions within their results. For more guidance on the data and the results specific to the enquiry boundary, please **call us on 0345 762 6848** or **email us at [groundstability@coal.gov.uk](mailto:groundstability@coal.gov.uk)**.

### Past underground coal mining

Details of all recorded underground mining relative to the enquiry boundary. Only past underground workings where the enquiry boundary is within 0.7 times the depth of the workings (zone of likely physical influence) allowing for seam inclination, will be included.

### Probable unrecorded shallow workings

Areas where the Coal Authority believes there to be unrecorded coal workings that exist at or close to the surface (less than 30 metres deep).

### Spine roadways at shallow depth

Connecting roadways either, working to working, or, surface to working, both in-seam and cross measures that exist at or close to the surface (less than 30 metres deep), either within or within 10 metres of the enquiry boundary.

### Mine entries

Details of any shaft or adit either within, or within 100 metres of the enquiry boundary including approximate location, brief treatment details where known, the mineral worked from the mine entry and conveyance details where the mine entry has previously been sold by the Authority or its predecessors British Coal or the National Coal Board.

### Abandoned mine plan catalogue numbers

Plan numbers extracted from the abandoned mines catalogue containing details of coal and other mineral abandonment plans deposited via the Mines Inspectorate in accordance with the Coal Mines Regulation Act and Metalliferous Mines Regulation Act 1872. A maximum of 9 plan extents that intersect with the enquiry boundary will be included. This does not infer that the workings and/or mine entries shown on the abandonment plan will be relevant to the site/property boundary.

### Outcrops

Details of seam outcrops will be included where the enquiry boundary intersects with a conjectured or actual seam outcrop location (derived by either the British Geological Survey or the Coal Authority) or intersects with a defined 50 metres buffer on the coal (dip) side of the outcrop. An indication of whether the Coal Authority believes the seam to be of sufficient thickness and/or quality to have been worked will also be included.

### Geological faults, fissures and breaklines

Geological disturbances or fractures in the bedrock. Surface fault lines (British Geological Survey derived data) and fissures and breaklines (Coal Authority derived data) intersecting with the enquiry boundary will be included. In some circumstances faults, fissures or breaklines have been known to contribute to surface subsidence damage as a consequence of underground coal mining.

### **Opencast mines**

Opencast coal sites from which coal has been removed in the past by opencast (surface) methods and where the enquiry boundary is within 500 metres of either the licence area, site boundary, excavation area (high wall) or coaling area.

### **Coal Authority managed tips**

Locations of disused colliery tip sites owned and managed by the Coal Authority, located within 500 metres of the enquiry boundary.

### **Site investigations**

Details of site investigations within 50 metres of the enquiry boundary where the Coal Authority has received information relating to coal mining risk investigation and/or remediation by third parties.

### **Remediated sites**

Sites where the Coal Authority has undertaken remedial works either within or within 50 metres of the enquiry boundary following report of a hazard relating to coal mining under the Coal Authority's Emergency Surface Hazard Call Out procedures.

### **Coal mining subsidence**

Details of alleged coal mining subsidence claims made since 31 October 1994 either within or within 50 metres of the enquiry boundary. Where the claim relates to the enquiry boundary confirmation of whether the claim was accepted, rejected or whether liability is still being determined will be given. Where the claim has been discharged, whether this was by repair, payment of compensation or a combination of both, the value of the claim, where known, will also be given.

Details of any current 'Stop Notice' deferring remedial works or repairs affecting the property/site, and if so the date of the notice.

Details of any request made to execute preventative works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991. If yes, whether any person withheld consent or failed to comply with any request to execute preventative works.

### **Mine gas**

Reports of alleged mine gas emissions received by the Coal Authority, either within or within 500 metres of the enquiry boundary that subsequently required investigation and action by the Coal Authority to mitigate the effects of the mine gas emission.

### **Mine water treatment schemes**

Locations where the Coal Authority has constructed or operates assets that remove pollutants from mine water prior to the treated mine water being discharged into the receiving water body.

These schemes are part of the UK's strategy to meet the requirements of the Water Framework Directive. Schemes fall into 2 basic categories: Remedial – mitigating the impact of existing pollution or Preventative – preventing a future pollution incident.

Mine water treatment schemes generally consist of one or more primary settlement lagoons and one or more reed beds for secondary treatment. A small number are more specialised process treatment plants.

### **Future underground mining**

Details of all planned underground mining relative to the enquiry boundary. Only those future workings where the enquiry boundary is within 0.7 times the depth of the workings (zone of likely physical influence) allowing for seam inclination will be included.

### **Coal mining licensing**

Details of all licenses issued by the Coal Authority either within or within 200 metres of the enquiry boundary in relation to the under taking of surface coal mining, underground coal mining or underground coal gasification.

### **Court orders**

Orders in respect of the working of coal under the Mines (Working Facilities and Support) Acts of 1923 and 1966 or any statutory modification or amendment thereof.

### **Section 46 notices**

Notice of proposals relating to underground coal mining operations that have been given under section 46 of the Coal Mining Subsidence Act 1991.

### **Withdrawal of support notices**


Published notices of entitlement to withdraw support and the date of the notice. Details of any revocation notice withdrawing the entitlement to withdraw support given under Section 41 of the Coal Industry Act 1994.

### **Payment to owners of former copyhold land**

Relevant notices which may affect the property and any subsequent notice of retained interests in coal and coal mines, acceptance or rejection notices and whether any compensation has been paid to a claimant.



The map highlights any specific surface or subsurface features within or near to the boundary of the site.



Key

- Approximate position of the enquiry boundary shown
- Disused mine shaft
- Disused adit
- Outcrop (Proven)
- Opencast mine licence area
- Unlicensed opencast site
- Site investigations

How to contact us

0345 762 6848 (UK)  
+44 (0)1623 637 000 (International)  
[www.groundstability.com](http://www.groundstability.com)

## GENERAL NOTES

1. Earth Science Partnership (ESP) believes that providing information about limitations is essential to help clients identify and therefore manage their risks. These risks can be mitigated through further investigation or research, but they cannot be eliminated. This report may not be used for any purpose other than that for which it was commissioned.
2. This report includes available factual data for the site as obtained only from the sources described in the text. The data are related to the site on the basis of the site location and boundary information provided by the client. The findings and opinions conveyed in this assessment are based on the information obtained from a variety of sources as detailed in the report, which ESP believe are reliable. Nevertheless, ESP cannot and does not guarantee the authenticity or reliability of the information it has relied on. It is possible that the assessment failed to indicate the existence of further sources of information on the site. Assuming such sources do exist, their information could not have been considered in the formulation of the opinions and findings in this report. It should be recognised that different conditions on site may have existed between and subsequent to the various map surveys.
3. In preparing this report it has been assumed that all past and present occupants of the site have provided all relevant and other information, especially relating to known or potential hazards. This report is not required to identify insufficiencies or mistakes in the information provided by the user/owner or from any other source, but has sought to compensate for these where obvious in the light of other information.
4. Reports are normally prepared and written in the context of a stated purpose, and should not, therefore be used in a different context. Furthermore, new information, improved practices and legislation may necessitate an alteration to the report in whole or in part after its submission.
5. The opinions presented in this report are based on the findings derived from a site inspection, investigations and a review of historical and other records. The report details any indicators that may suggest that hazardous substances exist at the site at levels likely to warrant mitigation. Not finding such indicators does not mean that hazardous substances do not exist at the site. The most recent site inspection was undertaken as detailed within the report. Circumstances on sites are subject to change and certain indicators of the presence of hazardous substances that may have been latent at the time of this inspection may subsequently have become observable.
6. The work carried out for the assessment can only investigate a small portion of the subsurface conditions. Certain indicators or evidence of hazardous substances may have been outside the limited portion of the subsurface investigated, latent at the time of the work or only partially intercepted by the works, and thus their full significance could not be appreciated. In this regard, groundwater levels are particularly susceptible to variation and it should be noted that groundwater levels are subject to diurnal, seasonal, and climatic changes and are solely dependent on the time the ground investigation was carried out and the weather before and during the investigation.
7. Accordingly, it is possible that the assessment failed to indicate the presence or significance of hazardous substances. Assuming such substances exist, their presence could not have been considered in the formulation of the report's findings and opinions. The conclusions resulting from this study and contained in this report are not necessarily indicative of future conditions or operating practices at or adjacent to the site. Where differing ground conditions or suspect materials are encountered during future site works, additional specialist advice should be sought to assess whether the new information will materially affect the recommendations currently provided herein and whether further consideration is required. Any limiting factors should be assessed by an appropriately qualified specialist.
8. The assessment was prepared for the sole internal use and reliance of the Client. The report shall not be relied upon by or transferred to other parties without the express written authorisation of the Earth Science Partnership. If an unauthorised party comes into possession of the report, they rely on it at their peril and the authors owe them no duty of care and skill.
9. The copyright in this report and other plans and documents prepared by the ESP is owned by them and no such report, plan or document may be reproduced, published or adapted without their consent. Complete copies of this report may, however, be made and distributed by the Client as an expedient in dealing with matters related to its commission.