



Second Floor - Protective Services

First Floor - Protective Services

1:50

ire Alarm Panel

Security Alarm Panel SAP

Disabled Refuge Panel DRP

Disabled Toilet Alarm Panel DTA

ire Break Glass

IONS

| Suitable for Review and Comment | 13/03/24 | AM | DF AH |
|---------------------------------|----------|--------|-----------|
| Review Description | Date | Review | Checklist |

| Revision Description | Date | Drawn By | Checked | Approved By |
|---|---|--|---------|-------------|
|  Hydrock |  | 3rd Floor, Wharton Place 13 Wharton St Cardiff CF10 1GS t: +44(0)2920 023665 | | |

e: cardiff@hydrock.com

ECT erthyr Synagogue

Electrical Services

Protective Services Layout First Floor & Second Floor

| | |
|-----------------------------------|------------|
| LOCK PROJECT NO. | SCALE @ A0 |
| 464 | 1 : 50 |
| US DESCRIPTION | STATUS |
| NOT SUITABLE FOR REVIEW & COMMENT | S3 |

| | |
|------------------------|----------|
| VERSION NO. | REVISION |
| 24-HYD-XX-XX-DR-E-4001 | P01 |