













**NOTES**

- This drawing is copyright and may not be reproduced without the permission of Mann Williams.
- All drawings are to be read in conjunction with the project specification with all works carried out in accordance with the latest British Standards and codes of practice.
- Any ambiguities or discrepancies between this drawing and any other information given elsewhere must be reported to Mann Williams for clarification before work proceeds.
- All dimensions to be checked on site and any discrepancies reported to the engineer before work commences.
- Only figured or calculated dimensions should be used and no drawing, in any format should be scaled.



**CDM RESIDUAL STRUCTURAL AND ENVIRONMENTAL RISKS**

1. Risk of undermining existing wall footings during excavations for lift pit.

**In accordance with the Contractors (Design & Management) Regulations 2015, Mann Williams has undertaken a design risk assessment for the elements of work shown on this drawing, residual risks are identified above.**

REV	DESCRIPTION	BY	DATE
P1	PRELIMINARY	JB	28.02.24

**PROJECT**  
**MERTHYR TYDFIL SYNAGOGUE**

**TITLE**  
**STRUCTURAL DETAILS - SHEET 1**

**MANN WILLIAMS**  
CONSULTING CIVIL AND STRUCTURAL ENGINEERS  
53 MOUNT STUART SQUARE  
CARDIFF CF10 5LR  
T 02920 480333  
F 02920 435920  
E cardiff@mannwilliams.co.uk

DRAWN BY CHECKED BY SIZE SCALE DATE

JB PR A1 AS SHOWN 27.02.24

STATUS

**PRELIMINARY**

PROJECT 9684 DRAWING 301 REV P1