Sequence Area 11
Re-grade of surface weathered stone. Fill placed against working face. Rock gutter along full length of fill

Sequence Area 12
Grade back upper section of face to stabilise fault affected zone. Fill placed against working face with scree-cone to stabilise faulted area. Rock gutter along full length of fill.

Factory
A4060
Track
411m
385m
380m
Spreads
FB
Spr
Iss
Drain
Trial Pit

0 10 20 30 40 50 75 100 125 150 200 250 m

Based upon the Ordnance Survey VectorMap Local with the permission of the Controller of His Majesty's Stationery Office, Crown copyright reserved. Licence No. 100004963

Eglurhad / Key:

- Application site boundary
- Previously restored land
- Regraded area
- Scree area
- Active restoration works [CUT]
- Active restoration works [FILL]
- Surface contours (interval: major 25 m, minor 5 m)
- Likely direction of working

Cywi. Rev.	Dyddiad Date	Disgrifiad Description	Gan By	Gwiriwyd Checked	Cymer. Appro.
02	17/01/2025	issued for Planning	RhE	JS	JS
01	13/11/2024	issued to Client for comment	RhE	JS	JS

Cleient / Client:

MERTHYR (SOUTH WALES) LTD

Enw project / Project name:

FFOS-Y-FRAN
FINAL RESTORATION STRATEGY

Teitl lluniad / Drawing title:

Figure 4.3 - Working Plan B
Sequence Area 11 and 12

Darparwyd gan / Prepared by:

RML
1 Llys Clwyd, Cwrt Y Dderwen, Ffordd Celyn, Ruthin, Denbighshire, LL15 1NJ
Rhif Ffon/Tel: +44 (0)1824 704366, Ffacs/Fax: +44 (0)1824 705450
e-bost/e-mail: rml@rmlconsult.com, Gwefan/Website: www.rmlconsult.com

Graddfa / Scale (A1):	Dyddiad / Date:	Darlunwyd gan: Drawn by:	RhE
1:2,500 @ A1	Nov 2024	Gwiriwyd gan: Checked by:	JS
Rhif lluniad / Drawing number: 3274-RML-DR-L-53B		Cywiriad: Revision:	02

© Richards, Moorehead & Laing Ltd