

15. CYFARTHFA PARK WAYFINDING AUDIT

Entrance - Gurnos Road Bottom

2 Locations



LOCATION 1

Category: Entrance

Notes: No clear pedestrian entrance marker at this point, only opening times

Proposed sign type: Entrance panel

///snow.shirts.values



LOCATION 2

Category: Directional

Notes: Replace with new

Proposed sign type: Finger post

///fleet.spring.carry