

**Ground Control Limited**

Kingfisher House
Radford Way
Billericay
Essex CM12 0EQ
T 01277 650 697



Quotation for Extra Works

Date:	02/08/2023
Property Name:	Pontsarn STW
FAO:	Lee Banks

GC Ref:	573128.GB.23
GC Contact:	Greg Brown

H&S Risk	
Personal Injury:	High
Property Damage:	Low

Description of Works

There is a 35 metre mixed species tree line (Predominantly Maple, Alder, Willow and Ash) that is encroaching onto the access track and causing damage to the tanker/sludge vehicles as shown on attached photographs. The trees require uplifting to 5.2 metres over the access track only as highlighted in Yellow on attached map. Due to the trees being located on the woodland edge, the uplift works will compliment the balancing of the crown and therefore no further pruning required to the trees. All works to be undertaken by a qualified arborist team using long reach pruning rods and extendable chainsaws. All cuts to be undertaken in accordance with BS:3998 and target oroned to collar/node. All waste to be processed through a woodchipper





